

The Strain Gauge

James K Beard, Ph.D.

Rowan Hall Auditorium

beard@rowan.edu

<http://rowan.jkbeard.com>

November 2, 2006

What is Strain?

- Strain is elongation or deformation of a solid body due to forces applied to it
- Physical units of strain or delta length over length
- Practical units of strain for stretching or compression stress is microstrains, or parts per million of elongation
- Compression is denoted by negative strain

What is a Strain Gauge?

- Uses resistance of magnet wire
- Resistance increases as it stretches
- Resistance of a medium:

$$R_0 = \frac{\sigma \cdot Length}{Area} = \frac{\sigma \cdot Length^2}{Volume}$$

- If the volume stays constant as the wire is stretched an incremental amount δL , the resistance increases

Resistance vs. Stretching

- Resistance increases as it stretches

$$R = \frac{\sigma \cdot (\text{Length} + \delta L)^2}{\text{Area}}$$

$$\approx \frac{\sigma \cdot (\text{Length}^2 + 2 \cdot \text{Length} \cdot \delta L)}{\text{Area}}$$

$$= \left(1 + 2 \cdot \frac{\delta L}{\text{Length}} \right) \cdot R_0$$

The Gauge Factor

- Actual strain gauge resistance is

$$R = \left(1 + K \cdot \frac{\delta L}{Length} \right) \cdot R_0$$

- The factor K is the *gauge factor*
 - Theoretical value is 2
 - Actual value can vary due to
 - Physics of stretching
 - Temperature
 - Backing, adhesive
 - Small differences during manufacturing
- Calibration of the gauge factor is necessary for best accuracy

Practical Aspects of Strain Gauge Configuration

- Requirements
 - Must be easy to apply to material
 - Must be easy to use
 - Must have minimal effect on the strain being measured
- Configuration
 - Make very small
 - Physically weak compared to most materials
 - Satisfy ease of application and minimal effect on strain
 - Use folded configuration instead of straight wire
 - Keep total strain gauge size small
 - Measure the strain over a small area
 - Addresses all three requirements

How Strain Gauges are Used

- Apply so that strain-measuring wires are in the direction of the strain being measured
- Connect the strain gauge in a Wheatstone bridge circuit
- Measure the differential resistance
- Convert the differential resistance to strain for recording the measurement



The P-3500 Strain Indicator




Usage of the P-3500

- We have two for Sophomore Clinic
- Use will be under supervision of a faculty member
- Today we present strain gauges and the P-3500
 - How a strain indicator works
 - How they are hooked to the P-3500
 - How the P-3500 is used

What the Strain Indicator Is

- Battery-powered
- Electronics to
 - Put the strain gauge in a Wheatstone bridge
 - Balance the bridge for zero strain
 - Measure the output of the Wheatstone bridge
 - Calibrate a four-digit display to read strain in microstrains
 - Provide a ground-referenced analog output



BATTERY

OUTPUT

INSTRUMENTS DIVISION
KALSOB, NORTH CAROLINA, USA

P-3500
STRAIN INDICATOR

TRIA

P+

P-

S-

S+

D100

D500

GND

AMP ZERO

0.0000

GAGE FACT

0.0000

BALANCE

0.0000

MULT BRIDGE


POWER OFF AMP ZERO GAGE FACTOR RUN CAL 5000 $\mu\epsilon$ BRIDGE OFF X1 1/4-1/2

SERIAL NO. 8138178


How a Strain Gauge Indicator Works

- Provides a Wheatstone bridge
 - Resistance is the nominal resistance of the strain gauge
 - One of the other resistors is varied to balance the bridge for zero strain
- A differential amplifier captures the output of the Wheatstone bridge
- A variable gain calibrates the output to microstrains
- A display provides recordable data in microstrains
- An analog output provides data for oscilloscopes, data loggers, or other purposes


Strain Indicator



Wheatstone Bridge




Differential Amplifier



$$Gain = \left(1 + \frac{2 \cdot R}{R_G} \right) \cdot (e_+ - e_-)$$


How to Operate

- Instructions on the inside of the lid
- We use four buttons
 - Power off
 - Zero amp
 - Gage factor
 - Run




P-3500 STRAIN INDICATOR


MEASUREMENTS GROUP
INSTRUMENTS DIVISION
RALEIGH, NORTH CAROLINA



QUARTER BRIDGE
INTERNAL DUMMY



HALF BRIDGE





FULL BRIDGE

Tension in active arm A or compression in arm C gives positive reading.


1. Connect gages as above. Set BRIDGE pushbutton to proper position.
2. Depress AMP ZERO pushbutton. Set AMP ZERO control for reading of ± 0000 .
3. Depress GAGE FACTOR pushbutton. Set GAGE FACTOR controls in accordance with gages in use. Lock GAGE FACTOR knob.
4. Depress RUN pushbutton. Set BALANCE controls for reading of ± 0000 . Lock BALANCE knob.
5. Load gage system as desired. Meter reads in microstrain ($\mu\epsilon$).
6. CAL pushbutton connects $+5000\mu\epsilon$ shunt resistor across internal dummy. (See manual for optional uses of CAL pushbutton.)
7. BR EXCIT OFF pushbutton removes excitation from bridge circuit. (Not normally used with "remote sense" feature. See manual.)
8. MULT pushbutton extends measurements range to $\pm 199,990\mu\epsilon$. (Meter reads in increments of $10\mu\epsilon$.)

TRANSDUCER CONNECTOR




OPTIONAL CAL CIRCUIT
(SEE MANUAL)


P-3500



QUARTER BRIDGE
INTERNAL DUMMY

Tension in active a







In Use



For the Hoistinator

- Carefully select a spar for instrumentation
- Carefully select a point on the spar for a strain gauge
- Attach a strain gauge to the spar
- Relate measured strain to spar performance
 - Strain versus load
 - Failure strength
 - Failure load
- Relate measured strain to Hoistinator performance
 - Maximum safe load
 - Failure load

REMEMBER ENGINEERING SAFETY MARGINS